## **Lighthouse Home Inspection Report**

The main purpose of the Lighthouse home inspection is to provide clients with a better understanding as to the general condition of the home. A visual inspection of the building and its immediate grounds has been conducted in accordance with the pre-inspection agreement and the standards of practice in the home inspection industry. The facing pages outline general information and the Lighthouse standard of practice. This information forms an integral component of the inspection results and should be reviewed thoroughly in conjunction with the personalized sections of the report. The home inspection report is confidential and was prepared for the exclusive use of the client as identified in the agreement.

Summary		
Address of Inspection: 707 Hills dag	le Ave, E. Toronto	
Date of Inspection: Nov. 24//6Approximate	start time: 10,000 A.M. P.M. (circle) stop time 12,50 A.M. P.M.	
Recent WEATHER conditions: cloudy	wet ShouRain past 3 days: Yes Light No	
Weather at start of inspection:	Ground ConditionWetDrySnow	
Approximate outside temperature during the inspection	C. & prior to inspectionC.	
Front of Building facing:NorthSouthEastWes	st In Attendance:ClientHomeownerOther	
General Accessibility:Excessive storageConstr	ruction in progressSystems winterized	
Utilities turned offOccupied room or section	Access deniedOther	
Reference: Item & Page Number		
	Basement & Crawl Space 22	
General Structure & Roofing 4	Basement & Crawl Space 22	
Chimneys & Roof Drainage 6	Water Penetration & Internal Structure 24	
Vehicle Parking 8	Laundry & Wet Bar 26	
Exterior 10	Kitchen and Appliances 28	
Additions 12	Bathrooms 30	
Additions		
Grounds & Air Conditioning 14	Fireplaces & Common Safety Devices 32	
Electrical 16	General Interior 34	
Plumbing 18	Attic & Ventilation 36	
Plumbing 18	Aut & Ventilation	
Heating 20	Insulation 38	
	the territory of the second se	

Please note some deficiencies in the home may not be included on this summary page. Items that do not pose immediate safety hazards may be observed and omitted from this page.

The overall, general habitability of this home, taking into account the entire report, is in the opinion of the inspector:

Great solid home, excellent shape. Very well

maintained. Some minor typical issues.

If you have any questions, we encourage you to contact your inspector at

Page 2 of 38

Copyright © 2015 Lighthouse Inspections

## General Structure & Roofing

Building Style	Roofing
Detached	Roof Style(s)GableShedHipFlat
Semi- Detached	Mansard Gambrel Ridge Pitched
Townhouse	
Condominium / Apartment	Roof Covering(s) Asphalt Shingles Tar & Gravel Wood Shingles Metal Rolled Slate / Clay Tiles
Bungalow	Rubberized Membrane
2 Storey	
Split Level	Estimated life span:YoungerMid-life
2nd floor extends out beyond 1st floor	Older or End of useful life Number of layers
Estimated Age:Under 10 years	
10-2525-6060+over 70 years	Inspection Method: From ground with binoculars from a window from roof edge
Occupancy: Occupied Vacant Staged	Identified the following conditions:
General Construction:	lifting / clawing / cupping / curlingbubblingdirty
Wood FrameMasonry	particulate releasing dried, brittle / crumbling
	broken / missing partsother roof covering deterioration excessive moss or mold growing on roof
Flashing	waves and dips noted between structural members, see ATTIC
	section of report
Material None noted unknown metal Rubberized membrane Galvanized	Section of report
Material not determined	Younger roof covering indicators:
Defects: Appears to be patched	cleanfresh colourlaying smooth
Pieces damaged / loosePieces missing	dying antour
From interior, stains or wet spots indicate possible	Inspection Limitations:
leaking at or near flashing	The portion of roof was not visible to the inspector
Limitations:% not visible	and should be inspected by a roofing contractor to determine condition
Course of Action:	Roofing is mostly snow coveredFlat roof is covered by decking and could not be inspected
	Leaks see Moisture and water penetration in ATTIC section of report.
Skylights & Roof Windows	
None noted on exterior of house	Course of Action
# of units noted	Recommend roofing contractor reroof
Type:DomedFlushRoof Curb identified	Recommend roofer
Material:glassplasticunknown material	
Patching noted around unit on roof	Soffit & Fascia
Evidence of condensation noted	Soffit:aluminumwoodplastic
Caulking around unit:appears adequate	PaintedPaint deterioratedMould
missing or damaged, recommend repair	Rottedlooseevidence of leaksrustcorrosion
Defects noted:Cracked	Fascia:aluminumwoodplastic
Glazing:double or triplesingle, requires repair	PaintedPaint deterioratedMould
Skylights and Roof Windows are also identified on Interior section of report.	Rottedlooseevidence of leaksrustcorrosion
Additional Comments or Issues:	
Track read disease of	

Course of Action: Have a roofing or other appropriate contractor repair any deficiencies noted above.

# Chimneys & Roof Drainage

Chimney	Drainage
Brick Block Stone Metal	Nothing noted to direct roof run off
Chimney is covered, limiting inspection	On roof diverters were noted
Clearance sufficient above roof	
Decommissioned chimney; non-standard, have removed/sealed	
Chimney saddle on roof above chimney	Gutters and Downspouts
High Efficiency exhaust	Material: AluminumCopperPlasticOther metal
Number of chimney(s)  High Efficiency exhaust  Missing or loose mortar Cracks	Material
Flue linerobserved crackedmissing	Defects:
1 1	LooseBrokenOut of adjustment
Clean-out: located 695ement	Remove debris which is sticking out of system
operableUnable to operate, have repaired	Stains over outer gutter edge indicate overflow, system may be
Clean-outDirtyDamagedBlocked	clogged or undersized
Chimney can / wash observed Broken / damaged	Leaking observed at:
Chimney cap / washobservedBroken / damagedCap overhanging to protect brickNone noted	DrainsDownspoutsCorners of gutters
Rain Cap / Spark ArresterNone noted	
	Discharge: (reseal)
Defects Observed:	Discharges onto ground
CrackedLooseDamaged	Discharge extended 6 feet from foundation
Deterioratednot visible	Discharges into pipe or hole in ground
Flashing at chimney secure	Did Did not determine where pipe exits
LooseDamaged, repair / reseal / replace	Recommend change to ground discharge
	V
BEFORE USE, have chimney sweep clean, further evaluate &	Sufficient number of downspouts
repair as needed.	Add downspout at:FrontRearLeftRight sideDownspouts blocked
Temporary / non-standard repair observed, recommend mason evaluate and repair as needed.	DOWNSpouls blocked
mason evaluate and repair as needed.	Gutters:
Course of Action:	RustyHolding water (adjust)
	Clean gutters
Exterior Ventilation	
Times Oakla End Venta Bidge Vent Coffit Vent	Course of Action:
Types:Gable End VentsRidge VentSoffit VentWindowsAttic fan(s)Roof ventsTurbines	Course of Action: Recommend add / adjust splash blocks
Self opening & closing louvered vents.	Recommend add extensions to downspouts to direct water
	farther away from foundation
Side Walls:	Recommend redirect water discharge off lower roof – connect
No evidence noted to indicate need to increase ventilation	with lower gutters or direct to ground discharge
Spalling brickMould/mildew spores	Downgrout missing, re-install
Peeling or stained paint on exterior siding seems to indicate more ventilation is needed in side walls for the house to breathe better	Downspout missing, re-install Water penetration noted, make appropriate repairs
Yenniadon is needed in side wans for the node to breathe better	
	Have the appropriate type of contractor make repairs as needed
Course of Action:	to the above components
Recommend adding ventilation	
Additional Comments or Issues:	
Additional Comments or Issues:	

Course of Action: Have a roofing, masonry, or other appropriate contractor evaluate and repair as needed.

### Vehicle Parking

Driveway	Garage
None notedAsphaltConcreteStone or gravel	None Noted
	Estimated Size: Car(s)
Defects noted:	Bays are: side by side tandem
Depressions or holes pose a trip or safety hazard and should	Attached living space above
be corrected.	Semi-detachedDetached
Slope to building directing water to building or into garage,	Interior accessed: Yes No because
should be corrected.	Visibility limited by: Parked car Storage
Trench drain should be added across width of garage	( excessive
Crumbled/damaged surface may indicate water damage from (	Floor: Concrete Asphalt Dirt
under driveway surface.	normal condition
	Defects:CracksDepressionsOil stained
Course of Action:	Deteriorated surfaces (uneven surface)
	Walls:Masonry > Wood framed
<del></del>	Framingexposed to viewblocked by storage / walls finished
04-2-11-4-70	Exterior finishes deteriorated, replace
Other Parking Area Frond	
None notedNot determinedOn street Pq d	Automobile doors: Overhead Swinging
Off streetCommon parking area	Number:such doorsdeterioratedNot-operated, becausedeteriorated
Carport	Electric opener noted
X None Noted	operatednot operated, because
	Applied resistance and doordiddid not stop or
Size: Car(s)	reverse, as expectedAdjust sensor
Attached Semi-detached Detached	Missing safety cables inside of overhead garage doors
Visibility clear	springs, have contractor install.
Visibility obstructed by:Parked carStorage	
	Man doors:into houseto exterior
Floor:ConcreteAsphaltDirt	#operated
Normal condition	Replace weather sealRequires proper step(s)
Defects:Oil Stained	Self Closing door?YesNoAdd
Deteriorate surfaces	Not operated, because
Weller Vertical currents only Open to weather	Results:
Walls:Vertical supports onlyOpen to weather	Windows: Mana fixed energiand
Enclosed on #sides	Windows: None fixed operational
Roof underside:Framing and sheathing exposed to view	Not tested, because Results:
from insideStored items restrict viewing	results.
Total mondootoroa nomo rocuror vormig	Roof underside:Framing and sheathing exposed to view
Water Penetration: Water stains	from insideDrywallStored items restrict viewing
Water leaking throughDamaged members	
	Enclosed attic:AccessNo access
Attic:Enclosed attic:AccessNo access	EnteredYes No
EnteredYesNo	
	Water Penetration:Water stains noted
	Water leaking throughDamaged members
Course of Action:	
	Gas-Proofing: Seal any openings in the finishing materials to
	minimize the potential for gas entry into the home
A Little and O assessment and I among the second	
Additional Comments or Issues:	

Course of Action: Have a home improvement or other appropriate contractor evaluate and repair as needed.

### Exterior

Wall Finishes	Foundation Walls
	Poured Concrete Block & Mortar Stone & Mortar
Location:AllMain FloorUpper floorUpper floorSide	Brick & Mortar Wood Stucco over unknown
Brick / MasonryWoodAluminum/VinylStucco	
Cement board EIFS (Exterior Insulation and Finish System)	Defects:
Evidence of Condensation presentYesNo	Cracks observed were smaller, monitor over time
General ConditionTypicaldeteriorated	Larger cracks were observed, recommend repair
General Condition Typical deteriorated	Larger erasite trees execute the same and the same a
Repairs RequiredUpper floorUpper floor	Vines, shrubs, trees or other planting obscuring the view
Location:AllWall FloorOpper floor	of the foundation. These plantings will restrict the inspection
FrontRearSide	scope and may be hiding significant defects.
Brick / MasonryWoodAluminum/VinylStucco	300pb and may be maing digitilisative actions.
Cement boardEIFS	
Evidence of Condensation presentYesNo	Structural
General ConditionTypicaldeteriorated	
Repairs Required	No major structural defect evidence was noted, appears in
	normal condition for its age
Finish too close to grade, repair	Major structural defect evidence was noted, as described:
Vines, shrubs, trees or other planting obscuring the view	The second state of the second
of the wall finish. These plantings will restrict the inspection	Course of Action:
scope and may be hiding significant defects.	
	Doors
Windows	
Normal condition for age of houseUpgraded	SolidHollow coreFrench doorsSliding glass
StormsScreensSome may be missing	Metal Wood fiberglass / composite
Loose or missing glazing should be replaced	Open & close as expected
Loose or missing caulk, have recaulked	Need adjustments to operate as expected
Trim, Observed:MouldDecay / rot	Broken door or parts need repairing/replacing
Re-seal sills	Missing/broken hardware to be installed/replaced/repaired.
Maintenance / repairs required at window frames	Reseal frames
waintenance / repaire required at window manner	Storm doors Operated:open & close as expected
Basement window(s):	Doors require adjustment to operate as expected
None noted Wood Metal Plastic	Trim, Observed:MouldDecay / rot
Sash are located high near ceiling	
and openinoutslide sideways	Wood to Soil Contact
and opennoutondo oldonayo	was was not observed
	was not asserved
Window Wells	201000
None noted	Location: garage
MetalWoodConcrete	
	Course of Action:
UncoveredCovered	Remove all decayed wood and raise any wood structure onto
Defects:BrokenCrackedCrumbling	concrete pavers as possible
Flooded Damaged cover	
Water Stains inside windows indicating poor drainage	Storage
D de dina well for drainage	Excessive storage at side of building, have removed
Course of Action: Recommend adding well for drainage	Wood piles against building, have removed, may provide
Cover should be installed/repaired to keep water out.	home to animals and insects.
Close down openings for safetyRe-secure to wall	nome to animals and insects.
Grade in well too high, lower	
Additional Comments or Issues:	

Course of Action: Have an engineer, Pest Control or other appropriate contractor rectify any deficiencies noted above

### **Additions**

Main Entry	Deck and Balcony
Location:	None noted
ConcretePorch ofwoodconcrete	Location: rear yard
stone with stepswalls enclose area	WoodMetalConcrete
Deteriorated/damaged steps / supports pose safety hazard	uneven and ri
#steps down from porch	# 5 Steps to grade to high (adj
Step rise(s) too high / uneven, adjust	Too close to grade to look under
Handrails/guardrails: ) (deteriorated)	Close to grade could only see under some sections
Nana nated Decrement and for a feb.	Sufficiently above grade to get under and look
None notedRecommend add for safety	No access below: Blocked byStored items
Loose or unsafe, recommend repair for safety  Railings too low by today's standards, add / adjust for safety	Plant growthElements(Snow, ice, water)  Defects:
Railings too low by today's standards, add 7 adjust for safety	
<b>W</b> -11	Uneven surfaces pose a trip hazard
Walkways	No bolts noted to attach to house Bolt to framing
None noted	Install missing / additional joist supports
	Support columns not attached to foundation
To Main entry:ConcreteAsphaltPavers	Take steps to reduce sway or deflection noted
SlateGravelInterlock / brick	Wooden piles / supports below soil, raise above soil level
Uneven/broken surfaces pose trip hazard	Wood flooring and/or structure deteriorated
	Improve supports as required
Other walks:ConcreteAsphaltPavers	
SlateGravelInterlock / brick	Handrails/guardrails:
Uneven/broken surfaces pose trip hazard	None noted Recommend add for safety
	Feel loose BrokenClose down openings for safety
Secondary Entry	Railings too low by today's standards, add / adjust for safety
None noted	
Location: right cide	Patio
Concrete slab Porch of wood concrete	None noted
stone with steps walls enclose area	
Deteriorated/damaged steps / supports pose safety hazard	Location: rear yard
# steps down from porch	Location:
Step rise(s) too high / uneven, adjust	Uneven/broken surfaces noted which pose trip hazard
Exterior below grade entry notedrequires proper step(s)	
Requires proper drain	
Handrails/guardrails:	Retaining Walls
None noted Recommend add for safety	None noted / decorative only
Loose or unsafe, recommend repair for safety	Wooden: Pressure treated
Railings too low by today's standards, add / adjust for safety	
Railings too low by today's standards, add / adjust for salety	The state of the s
<u> </u>	ConcreteBlockStoneBrick
Fences	Mortar joints observed
	Drainage holes to relieve water pressure from behind the wall
Other	areare not evident.
secure	
looseweakBroken sections	Defects:
Yard not fully fenced	BucklingBowingCrackingLeaning
Gate: operated self-closer install self-closer	Other displacement
X Inspector does not know ownership	
Additional Comments or leaves:	
Additional Comments or Issues:	

Course of Action: Have the above noted deficiencies corrected by the appropriate contractor

### **Grounds & Air Conditioning**

Grading	Air Conditioning
Within 6 feet of foundation:	None Noted
Front of house, slopes	1.21.1
towardaway from houseis relatively level,	Location: right side
Right of house, slopes	10:1
is relatively levelis relatively levelis	Brand name on central unit:
towardaway from houseis relatively level	Type:Central AirHeat PumpGas Chiller
Rear of house, slopes	Evaporative CoolerElectric Compressor
towardaway from houseis relatively level.	Roof or attic mounted (or other) system
Beyond 6 feet:	Ductless Air Conditioning system
Entire lot is relatively level	Water cooling system, recommend replace
Slopes away from house, acceptable	
Slopes towards the house, should be graded away	
Recommend grading slope to direct water a minimum of 6 feet	In use during inspectionOperated
rom foundation to minimize water penetration	Not seemed
General grading should be addressed as larger depressions	Not operated
an pose a trip hazard	(see opposite page for testing limitations)
Ravine lot, potential erosion concerns Recommend the following negative effect on the building is	
ddressed:	
dulessed.	Visible portion of equipment appears to be
General grading could not be assessed due to snow.	Newer Midlife Older
5.000.00	or ApproximatelyYears old
Trees, Shrubs, & Plantings	
rees, shrubs and other plantings near the home should allow the	Central unit appearslevelnot level
ome to breathe	Outdoor fan is:obstructed
None noted near house which appear to pose a possible	Outdoor grills are:damageddirty
azard to the house at the present time.	Have all debris removed before use
Planting(s) noted overhanging / touching /near to / climbing on	Compressor isnoisy
ouse	
hese conditions should be corrected, usually involving cutting back,	Ductwork
oruning or removal of the planting.	in common with heatingindependent from heating.
Other plantings, away from house, should be inspected by	
lient and attended to as needed	With unit running, house seemed to cool
	slowly quickly adequately not at all
Environmental	
Although not required as part of a Home Inspection, some evidence	Course of Action:
oticed by an inspector, which might indicate some environmental	Course of Action:
azard, chemical or oil spills:	
Dead foliage, out of season - looks unusual	
Dark stains on soilOil slick or stain on water	Individual room units observed
bandonedmotor vehicle(s)batteriesPaint cans Pipes into the ground may indicate buried storage tanks	operatednot operated
Out of use storage tanks	Results: received coolingdid not receive cooling
Homes of this era may have additional environmental	
nazards/concerns.(i.e., lead, asbestos, etc.) that are not visible to	
ne inspector	Course of Action:
Course of Action:	
Recommend further evaluation by an appropriate contractor	
pefore any renovations of the property.	7

Course of Action: Have a heating / cooling or landscaping contractor evaluate and repair as needed.

### **Electrical**

Main Service Entrance	Main Distribution Panel
Location: right side	Location basement
Location:UndergroundOverhead wires	Service Panel Rated /OD Amps
Overhead Contact Hazards observed:	100
obstructed / threatened / touched by tree / branches have hydro	Main Disconnect: / O O Amps
or a tree surgeon correct situation before damage occurs	Circuit breakerFusesKnife switch
	Location Main panel box Other
Meter	100
Service cable rated:Amps	Service SizeAmpsCircuit BreakerFuses
Rated110/120 Volts220/240 Volts	110-120 volt circuits: (number) <u>35</u> 15A20A30A
W (# wires in service)	220-240 volt circuits: (number)
	20A30A40A50A60A70A
Location: right side	Branch wiring
	CopperAluminumKnob & Tube
Distribution	BX Cable (Metallic sheathed) Romex (Non-metallic
Outlets, switches, lighting as observed and evaluated, throughout	sheathed)Not determined
the home. Random tested outlets, wall switches & installed lighting	As observed:inside panel box
and found the following evidence:	Circuits labeled?YesNoSome
no deficiencies were detected3 holes(Says grounded)	Panel has been upgraded from original
Material	Sub Panels None noted # noted,
Copper Aluminum Knob & Tube	Panel RatedAmps; Service SizeAmps
*Please note that Aluminum and/or Knob and Tube wiring may exist within the	Location
homes' system and not be visible to the inspector or reported due to the limited	
nature of such an inspection. Inspector cannot determine percentage of older wiring.	Defects:
	More than one wire attached to a circuit protector, have
Defects:	evaluated for safety by electrician
Ungrounded outletsReversed polarity	Abandoned wire(s)
Hot Ground reversed Dead outlets	Connections in panel box
Open groundOpen neutralOpen hot	Non-standard installation / upgrade, further evaluation
Open air connections	Water stainsRust
Missing safety covers on switches, outlets and junction boxes	Dead insects, may indicate cable entry not sealed properly
Loose connections Loose boxes Loose receptacles	Unprotected panel openings, recommend closing down
Lights did not light, missing or broken bulbsFlickering lights	Overloaded circuits Overfused breakers / fuses
Switches for which use not determined (frequently noted)	Loose connectionsinto the boxwithin the box
Loose hanging wires / otherwise dangerous conditions.	Damaged sheathing
Bare bulbs near / touching storage items, possible fire hazard	Discoloration of wires in panel, may indicate overloaded circuits
Move wires off heating ducts (secure)	Panel location non-conforming, needs to be addressed
Lighting at staircases is not sufficient	
In staircases with 3 or more steps, switches are not	Course of Action:
located at both the top and bottom of staircase.	Have an electrician install Arc Fault Interrupter (AFCI)
Decora style switches and outlets noted throughout system,	protection
have checked for proper installation with aluminum wiring	Panel may be overloaded, have evaluated and repaired as
Outlets with 2 slots (Older ungrounded style)	needed
Non-standard electrical noted	Have an electrician check panel and rectify deficiencies as
Interior grade wiring noted on exterior	needed.
Improper use of electrical cords	General Limitations
	X Concealed electrical components cannot be inspected
Course of Action:	Main disconnect cover could not be removed, common
Have an electrician check entire system and rectify	Panel cover could not be removed, common Panel cover could not be removed due to accessibility,
deficiencies as needed.	
ESA certificate may be recommended or required due to	recommend correct Power off insomeall areas
alone in one on longh and to be usiging	No access to:
aluminum or knob and tube wiring	In most cases, grounding termination point is not visible.

Course of Action: Have an electrician evaluate and repair entire system as required

Page 16 of 38

## Plumbing

Water Supply	Waste System
Entry Location Basement Closet	
Public	Pipes:ABS PlasticCast IronCopperLead
Meter Location Basement	Galvanized SteelBrassNot Visible
Private	Pipes observed roof + basement
_ocation of wellhead	Main waste line clean-outswerewere not observed
1 1 2 1	Cheater vent(s) noted
Main Shutoff valve: at ehtry	Ventingwaswas not observed extending through roof
,	and was was not seen in attic
Supply Pipes:CopperPlasticGalvanizedBrassLeadCould not determine	'S' traps noted in drainage system, should be rectified
BrassLeadCould not determine	No 'P' traps visible
Conditions requiring attention:	Conditions requiring attention:
	Leaks in waste system:
Distribution Pipes:CopperPlasticGalvanized	None notedactive leaksdry leak type stains
Brass Lead Kitec Unknown metal	were observed
Conditions requiring attention:	Odour noted at, have evaluated by
	plumber , nave evaluated by
	Discharge
Leaks in water supply systemNone noted	PublicPrivate Reported byVendorRealtorNot Determined
Rust / Corrosion noted	Reported by Vendor Realtor Not Determined
	Drain line exits at
Hose Bibs	
Number Noted	Waşte Ejectors
When turned on water came out, when turned off the	None Noted
vater did did not shut off fully.	Drain or waste ejector pumps were observed
When turned on water did not come out	Location
Not tested, because	Uncation When water was run the pump(s)did did not
nterior:	seem to pump out the water. Slow drainage was noted.
Hose bib shut off valve(s) located	Change ejector pipe to PVC/ABS
Did not locate at, locate and leave accessible	
Frost protected, interior shutoff may not be required	Domestic Water Heater
	Location_basement_unit enc
Functional Flow	V Doubel Owned unknown : Lie 10
	Estimated age / year 2003 and bol Make:
Not Tested because	Estimated age / year and bot
	Make:OilPropane
Method: With multiple fixtures running, flushed toilet(s) o over stress flow, observed decrease in flow:	GasElectricOiiPropaneNater on Demand systemIntegral with heating system
minimalacceptableexcessive	Rated Capacitygallons / Liters, which is generally
	ample for about
Hot Water Output:	Safety pressure release valve was was not observed
Hot water Output:  Hot water was was not received at hot water faucets	anddiddid not have safety extension down to floor.
hich were operated, in random testing, indicating the system	No Some Extensive rust / corrosion / water
is is not providing hot water to these faucets.	noted at base of unit indicates unit is leaking.
fter about minutes of running hot water at	noted at 2000 of with majorito with 10 founding.
2,4 Floor sink faucet, water coming from faucet was	Vent Pipe:doesdoes not slope or rise to exhaust
hot cold.	pipe looseconnection(s) loose
	rusted or deteriorated
	joint to exhaust in need of repair
Additional Comments or Issues:	

Course of Action: Have a plumber or other appropriate contractor repair / replace items noted as needed.

### Heating

General Heating System	Distribution
Fuel:	Ductwork / RegistersUnobserved Radiant
Gas Oil Electric Wood Propane	Baseboard heaters Thermostat(s)on unitson wall
Type:	RadiatorsBleed valvesLeaks / Corrosion
Forced Air Electric BaseboardElectric Radiant	Heat equal at both ends, indicates proper distribution within unit
Hot Water Radiant Boiler Steam Boiler Geothermal	Boiler system: pressure release valve extension missing
High efficiency mid-efficiency low efficiency	Heat supply & return PIPES:
Integral with water heater / water on demand system	CopperGalvanized Iron PlasticUnknown material
Approximate age/year of systemas evidenced by:	Observed in:basementcrawlspaceattic
tag	some most pipes not visible
Brand Name: Slant Fin	Heat Distribution:
Furnace not operated due to temperature (see opposite page	was not found in each room – add as needed
for testing limitations)	Distribution missing from:
Recommend Service Clean Furnace	Heat Recovery Ventilator (HRV) noted:working properly
Remove filler pipes for previous heating system	Recommend maintenanceRecommend service Course of Action:
Improve clearance around furnace for safety and access	Clean Ducts covered with tape
Previous oil tank notedOil line noted below surface, recommend further evaluation. Estimated age of oil tank	Insulation on heating pipes/vents, recommend test for asbestos
Add vent to furnace room	Seal gaps/joints at ductwork and plenum to maximize the
Corrosion/rust/water noted in furnace, evaluate and repair	efficiency of distribution system.
WHICH THE PARTY OF	officioncy of distribution system.
Controls	
Heating System was was not in use during inspection	Heat Exchanger
Thermostat(s) were locatedmain floor	Heat exchanger is hidden from view, inside the unit, and therefore
The system seems to be regulated by individual controls	cannot be inspected.
in each heated areaon the heating units themselves	The following evidence suggests that the heat exchanger may
When turned on by above thermostat(s)/control(s), units	be defective
fired or gave heatdid not fire or give heat.	
HRV control (s) located in	Filters N/A
A furnace electrical disconnect notedabovethe unit	Air Filter in warm air heating/cooling unit.
An automatic Shut-Off Safety Device(s) was noted	Washable DisposableElectronic HEPA
on the oil line attankburner	Location at furnace in return grill
	Not installed properly to correctly filter air
Energy Supply	None noted, have it located and evaluated or have installed
Gas, believed to be publicElectricity	by heating contractor.
Oil tank in basement _Fill pipes indicate possible buried oil tank	Heating contractor should rectify defects.
Gas, onsite, evidenced by white storage tank	Recommend non-allergy type filter
Entry Location	Filter appears clogged/blocked replace/clean
Gas meter location appears too close to vent/A/C, have checked	
by HVAC technicianBond gas line to proper ground	Oil Line Filter:
Fuel Leaks noted? No Yes	Located near entry into basementnear oil tanknear furnace
Flue Pipes	Oil filters should be serviced by a heating contractor annually
Flue pipes were identified	
	along with the oil heating unit.
DoDo not rise slightly to chimney / exhaust	along with the oil heating unit.  Humidifier
DoDo not rise slightly to chimney / exhaustSoints appear looseRusted or deteriorated	along with the oil heating unit.  Humidifier  None noted
DoDo not rise slightly to chimney / exhaustDoints appear looseRusted or deterioratedConnection to exhaust is loose or in need of repair	along with the oil heating unit.  Humidifier  None noted  Location:return ductheating duct
DoDo not rise slightly to chimney / exhaustJoints appear looseRusted or deterioratedConnection to exhaust is loose or in need of repairPipes too close to combustibles, recommend repair	Along with the oil heating unit.  Humidifier  None noted Location:return ductheating ductFilter appears cleanAdjust water level
DoDo not rise slightly to chimney / exhaustJoints appear looseRusted or deterioratedConnection to exhaust is loose or in need of repairPipes too close to combustibles, recommend repairSupplemental Heat	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnected
DoDo not rise slightly to chimney / exhaustJoints appear looseRusted or deterioratedConnection to exhaust is loose or in need of repairPipes too close to combustibles, recommend repairSupplemental Heat None notedSome noted	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replaced
DoDo not rise slightly to chimney / exhaust	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type
	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replaced
	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type Humidistat Located:
	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type Humidistat Located:
	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type Humidistat Located:
	Along with the oil heating unit.  Humidifier  None noted  Location:return ductheating ductFilter appears cleanAdjust water levelWorkingNot workingDisconnectedParts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type Humidistat Located:

Course of Action: Have a heating contractor rectify any defects noted above.

Page 20 of 38

### **Basement & Crawl Space**

Basement Basement	Basement Ceilings
Percent of lowest level	Exposed to viewHidden from viewPartial view
Finished Partially finished	Ceilings finished?
Exterior access / egressNone notedDirect walk out	Evidence ofPreviousActive leak
Up exterior stairway bulkhead	
	Crawl Space
Foundation walls: Covered Visible	None noted Percent of lowest level
Approximate percentage visible Limitations to a thorough inspection:	None noted Percent of lowest level Accessible Not Accessible
Limitations to a thorough inspection:	Entered Not Entered, because
StorageInsulationWalls finished / drywall / painted	Not Entered, because
Visible areas:BlockConcreteBrick & Mortar	Floors: concrete dirt
Stone & Mortar Stucco over unknown	Ventilation: noted none noted (add Ventilation)
Condition:	Floors:      concrete      dirt         Ventilation:      noted      none noted (add Ventilation)         Type:      wall vents      vents into basement
Satisfactory	Recommend adding ventilation to this are to prevent
Evidence of previous wall repair	condensation / moisture problems
Evidence of Provious Wall reputil	Additional ventilation recommended
Defects noted:	Evidence of moisture; determine source and repair as needed
Settlement cracks Minor Monitor over time	
Significant, have a mason repair	Insulation observed:YesNo; Adequate?YesN
Have cracks / leaky areas repaired to prevent ongoing leakage	Vapour Barrier:on warm side of insulation
Tlave clacks / leaky areas repaired to prevent origining leakage	None notedInstalled improperly
Basement Floors	Moisture Evidence:PresentNot noted
1	Water Penetration Evidence:notednone noted
concretedirt All	
Covered withtile sheet goodscarpetingpainted	Slab on Grade
Hardwood / softwood / laminated wood	Not ApplicablePercent of lowest level
	concrete wood unknown / not visible
Limitations to a thorough inspection:Storage	slab: at about grade levelslightly above/below grade
Floors finished / coveredExcessive Furniture	The support system below grade is not observed and is unknown.
Approximate percentage visible5%	The exterior perimeter of the slab, where visible, cracks
Satisfactory	werewere not notedNo areas visible
Defects:	Exposed interior floor coverings are of:concrete vinyl
Settlement Cracks in floor were noted which appear to	wall to wall carpethardwoodsoftwood
be:older	carpet less than wall to wall in coverage
small, probably not major defects at this time, which	Observedbrokenwarpedrippled
should be monitored over time to see if they worsen	floor coverings, which may indicate cracks in the slab.
larger major defects	
showing differential settlement heaving	Floor Drainage
	Floor Drainage observed:
Evidence suggests hollow under floor	Yes No
Evidence ofPreviousActive leak	did did not have protective perforated cover
Mainture Fuidames - Dresent - Met noted	Trap primer noted? Yes No
Moisture Evidence: Present Not noted	Evidence of trap cracked / broken
Water Penetration Evidence:notednone noted	Recommend install backflow preventer
	Recommend install backnow preventer
Futorior Comment Diago	Cold Room
Exterior Support Piers	
Not Applicable	Not Applicable
Support columns ofMetalConcreteWood	Install/replace weatherstripping at door
Stone Block Brick	Venting installedventing blocked, open and leave active
were observed under the	No venting, proper venting to be added
	It is not recommended to finish or partially finish a cold room.
Support columns condition looked Satisfactory	Revert area to original state.

Course of Action: Have a masonry or other appropriate contractor repair the above items as indicated.

Page 22 of 38

#### **Water Penetration & Internal Structure**

Water Penetration	Foundation Structure
No signs noted	Joists
Evidence indicates a one time flooding	Not visible
Some extensive evidence of ongoing water penetration	Steel
vas observed	
Evidence observed:	Conditiongooddefects noted, see below
Water stains on:	Span and beams appear adequate
On walls,at base of wallfloors	Defects Observed:
base of stairsaround furnace	Cracks / cuts that reduce effectiveness, repair
Efflorescence Rot	Joists span too large, add additional support
Microbial growth / mildew	Rot on joists has reduced strength, repair
Rust on nail heads/ baseboard heaters, etc.	Evidence of sagging floors that is,
Sump pump, see section	Minor / older, monitor over time for changes
Wall board damaged	Movement appears to be recent and/ or ongoing, add
Damp or wet floor coverings	additional supports
Lifting tile	Add (#)joist hanger(s)
Other	rida (ii)jolot ridingor(o)
Othor	Columns
imitations to inspection:	Not visible
Subfloor & carpetStorageFurniture	Wood steel poured concrete block / brick
	Appears to have been altered/removed have evaluated
Course of Astions	Condition:
Course of Action:	
Overall, stains indicate previous flooding	Columns appear sufficient and in good condition
Further evaluation necessary	Columns appear to have shifted, repair immediately
Repair current leak issues noted	Defects observed:
Further evaluation and testing for possible mould recommended	Rot
and remediation work performed as required)	Cracks have reduced strength, add additional support
General Dampness	Insect infestation appears to have compromised columns,
	repair immediately
None noted	Topul Initiodicity
Feels damp Smells damp	Comma Domana
	Sump Pump
Dehumidifier noted	None noted
ocation: basement	Location:
Dehumidifier was running during inspection	submersiblepedestal
Evidence that dehumidifier running continuously	Running continuously
Recommend use of dehumidifier in basement	
	ActivatedNot working
Basement Ventilation	Could not test unit  No water in the hole
Dasement ventuation	
	Not plugged in (Electrical)
None noted	Recommend backup system or alarm
	Operating properlySlowReplace
Туре:	
Louvered wall vents	Discharge
<u></u> ✓ Window 5	ExteriorStorm drainUnknownSewer connection
Area open to main and / or upper floors (open stairwell)	
Exhaust fan	Course of Action:
Air Exchanging unit	repair/replace
Other	install sump pump
	Redirect discharge
Course of Action:	install check valve
Add additional ventilation to reduce condensation / moist air	
Add additional ventilation to reduce condensation / moist air	
Add additional ventilation to reduce condensation / moist air	

Course of Action: All defects noted above should be corrected and/or monitored by an appropriate contractor

### Laundry & Wet Bar

Laundry Area	Laundry Tub
No laundry provisions noted Location:BasementMain floorUpper floorIn/near bedroomsIn bathroomIn/near kitchen	Tub Porcelain Steel Plastic Concrete Tub damaged / cracked, replace
Appliances: Laundry	Tub damaged / cracked, replace
Clothes Washer None noted Brand Age:NewerOlderMidlife Connections for water & drain were notedConnections not visible Condition of water hoses:SatisfactoryReplace  Electrical OutletNot grounded	Faucets:  Faucets hot and cold working properly  Faucets do not shut off fully  Hot and cold reversed, have a plumber repair  Drain securenot secure  No leaks noted  Leaks noted at faucetsbelow tub  Leaks at water lines
Replace outlet	
In use during inspection, performing normal cyclesOperated one cycle, heard water come in, splash, spin and pump outNot operated	None noted  Location:Additional sink onlyOther
Have an appliance repair contractor repair noted defects.  Electrical: Laundry	Electrical: Wet Bar
Ground Fault Interrupter None Noted Recommend add GFI's for safety	Ground Fault InterrupterNone NotedRecommend add GFI's for safety
Additional Comments or Issues:	

Course of Action: Have an appliance, plumber or other appropriate contractor evaluate and repair as needed.

Page 26 of 38

Copyright © 2015 Lighthouse Inspections

### Kitchen & Appliances

Location	Range / Cooktop IMM 4373903
BasementMain floorUpper floor	Brand: Style: Free Standing Built in
Cabinets	Fuel type:Electric GasOther
WoodenPlastic Laminate Other	Age: Newer Older Midlife
Cabinets are are not secure end of life	Not operated
Doors and drawers:function as expectedloose cabinets	In use during inspection, indicating portion being used is
missing hardwaremissing door or drawer fronts	performing its major function
broken drawerswarped doorsadjust doors	Operated and found that #burners gave heat and
Stored items affecting visibility as to condition at time of inspection	# did not give heat
were:MinimalExtensive	"did not give near
	Oven
Counter Tops	Brand:
Plastic Laminate Ceramic Tile Ceramic Tile Granite/Marble/Corian	Part of the stove Built in
areare not secureloose (unsafe)missing	Fuel Type:Electric GasSelf cleaning(Not checked)
large areas heat scorched or damaged	Age: Newer Older Midlife See Stove
Stored items affecting visibility of counter tops at time of	Not operated,
inspectionminimalabout normalextensive	In use during inspection, indicating the portion being used is
	performing its major function
Sink	
Stainless SteelPorcelainPlasticUndetermined material	Bake and broildiddid not give heat when turned on.
Ran the water and found leaks None noted Above the sink	Refrigerator MEADALIAY
below the sink. Have leaks repaired by plumber	Brand: May + ag 14540461AX
Sink chipped/cracked. Stopper/strainer waswas not noted	
	In use during inspectionOperated
Disposal	Not operated Section 1
None noted	Items in cooling section felt cool, in freezer section felt frozen
Brand horsepower	-indicates doing major functions
Leaks noted?YesNoHave leaks repaired by plumber	Features:lce maker Water & Ice through door Frost Free
Tested unit, results:	Magnetic Seal:Damaged / Broken
Ventilation	Dishwasher FN 220 10000 =
None Noted, other than doors and windows	Brand: Bosch FD820 1000 807
Fan integral with a built-in Microwave or cooktop	Age:NewerOlderMidlife
Exhaust fan appears to vent to exterior	Operated In use during inspection
Recirculates air within the roomLight	Operated In use during inspection Not operated items/storage in machine
When the components were turned on, they seemed to	Heard Did not hear water come in, splash and pump
perform their major function.	out, indicating that the appliance is doing its major functions
Fan sounds excessively noisy	Recommend relocate drain to sink side of P trap
Filters:ObservedNone Noted	Recommend secure unit
	Built in Microwave 10257792 1 D
Electrical	None noted None noted
Ground Fault Interrupter None Noted	Brand: Jehn Air
Recommend add GFI's for safetyat sink	Age: Newer Older Midlife
Inadequate number of electrical outlets	Heated container of water, indicating does major function
	Too close to cooktop, repair as needed
Kitchen Floor	Not operated,
LaminateVinyl TileCeramic Tile	Other Appliance
WoodCarpet	None noted
Normal amount of bounce excessive bounce noted	Brand:
Have a flooring contractor correct any defects or	Operated Not Operated
deficiencies noted in floor.	to the total of the second of

Course of Action: Have an appliance repair or other appropriate contractor repair any deficiencies noted above.

Page 28 of 38

#### **Bathrooms**

DATURGOMA: Design	BATHROOM 2: Full Partial
BATHROOM 1: Full Partial Location	BATHROOM 2: Location 2nd Full Partial
Location Dugement	Tub. Quilt in Log Tub. Nano noted
Tub:Built inLeg TubNone noted	Tub:Built inLeg TubNone noted
Shower:with TubStall	Shower:with TubStall
Enclosure:PlasticCeramic	Enclosure:PlasticCeramic
Seems adequately fastened to wallYes No	Seems adequately fastened to wallYes No
Missing/damaged grout Evidence of moisture behind tiles	Missing/damaged grout Evidence of moisture behind tiles
Sink(s): #/_ VanityWall HungPedestal	Sink(s): #/_ VanityWall HungPedestal
Feels adequately fastenedYesNo	Feels adequately fastenedYesNo
Toilet: Flushed, Feels adequately secured Yes No	Toilet: Flushed, Feels adequately securedYesNo
Bidet: None notedTurned on	Bidet: None notedTurned on
Feels adequately fastenedYesNo	Feels adequately fastenedYesNo
Damage:None NotedCracked / Chipped	Damage: None Noted Cracked / Chipped
Noted at Tub Shower Sink Bidet Taps	Noted atTubShowerSinkBidetTaps
Floor:VinylCeramic Tile	Floor: Vinyl Ceramic Tile
Soft or weak spots noted in floor	Soft or weak spots noted in floor
Vents: Window Exhaust Fan None noted	Vents: Window Exhaust FanNone noted
Coultier Around tub lobour of wells and floor is	Caulking: Around tub/shower at walls and floor is
Caulking: Around tub/shower at walls and floor is	Loose Mildewed MissingRe-caulk as required
Loose Mildewed Missing Re-caulk as required	
Leaks: None noted	Leaks: None noted
Noted at TubShowerSinkBidet	Noted at Tub Shower Sink Bidet From fixture From faucets
From fixtureFrom faucets	Floring Interest   County   Floring   Floring
Electrical: Ground Fault Interrupter Install GFI	Electrical: Ground Fault Interrupter Install GFI
No receptacles	No receptacles
	/
Plumbing noted on exterior wall, unacceptable	Plumbing noted on exterior wall, unacceptable
Eswitches too close, to	
tub/shower area (relocate	
	BATHROOM 4: Full Partial
BATHROOM 3:Full Partial	BATHROOM 4: Full Partial Location
BATHROOM 3:Full Partial	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted
BATHROOM 3: Full Partial Location  Tub: Built in Leg Tub None noted	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic
BATHROOM 3:Full Partial Location Tub:Built inLeg Tub None noted Shower:with TubStall Enclosure:PlasticCeramic	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic Seems adequately fastened to wall Yes No
BATHROOM 3:Full Partial Location Tub:Built inLeg Tub None noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYes No Missing/damaged groutEvidence of moisture behind tiles	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic Seems adequately fastened to wall Yes No Missing/damaged grout Evidence of moisture behind tiles
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNoMissing/damaged grout Evidence of moisture behind tiles Sink(s): # Vanity Wall HungPedestal	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic Seems adequately fastened to wall Yes No Missing/damaged grout Evidence of moisture behind tiles Sink(s): # Vanity Wall Hung Pedestal
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo   Missing/damaged groutEvidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo	BATHROOM 4: Full Partial Location Tub: Built in Leg Tub None noted Shower: with Tub Stall Enclosure: Plastic Ceramic Seems adequately fastened to wall Yes No Missing/damaged grout Evidence of moisture behind tiles Sink(s): # Vanity Wall Hung Pedestal Feels adequately fastened Yes No
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub: _Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo   Missing/damaged groutEvidence of moisture behind tiles Sink(s): # VanityWall HungPedestal    Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet: None notedTurned on	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub: _Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage: None NotedCracked / Chipped	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with Tub Stall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedYesNo Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with Tub Stall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted	BATHROOM 4:
BATHROOM 3:FullPartial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    LooseMildewedMissingRe-caulk as required Leaks:None noted	BATHROOM 4:
BATHROOM 3:	BATHROOM 4:
BATHROOM 3:	BATHROOM 4:
BATHROOM 3:	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet    From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	BATHROOM 4:
BATHROOM 3:	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet    From fixtureFrom faucets Electrical:Ground Fault Interrupter Install GFI    No receptacles	BATHROOM 4:
BATHROOM 3:Full Partial Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo    Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal     Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on     Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile    Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is    LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet    From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	BATHROOM 4:

Have all above items corrected by a plumber or other appropriate contractor before items deteriorate further.

# Fireplaces & Common Safety Devices

Geris noted in branch outlets	Fireplace # 1	Ground Fault Interrupter (GFI) Protection
Metal prefabricated	None noted _ O /	No GFIs noted in house wiringGFI(s) noted in panel box
Mesanry Metal prefabricated Wood Stove Insert Gas Insert User Metal Masonry Firebox: Metal Masonry Metal prefabricated Month of the Masonry Metal prefabricated Month of the Masonry Firebox: Metal Masonry Firebox: Metal Masonry Metal prefabricated Wood Stove Insert Gas Insert Working Pirebox: Metal Masonry Firebox: Metal Masonry Metal Prefabricated Month Masonry Metal Prefabricated Month Masonry Metal Prefabricated Month Metal Masonry Metal Prefabrica	ocation Main Hoor	GFIs noted in branch outletsGFI(s) noted on exterior
Gas Insert	MasonryMetal prefabricatedWood Stove Insert	
irrebox: Metal Masonry Trierbirok Joose mortar Abnormal openings (Cracks, missing grout, etc.) Broken or missing parts did did not observe flue liner Combustion air supply: Interior Exterior air Limitations: Fire burning area blocked, unable to inspect Plot light was off during inspection Coation Masonry Metal prefabricated Wood Stove Insert Gas Insert Firebox: Metal Masonry Firebrick Joose mortar Abnormal openings (Cracks, missing grout, etc.) Abnormal openings (Cracks, missing grout, etc.) Broken or missing parts did did not observe flue liner Combustion air supply: Interior Exterior air Combustion air supply: Interior Exterior air Limitations: Fire burning area blocked, unable to inspect Pilot light was off during inspection Coation Have WETT Certified contractor clean, test, evaluate and coartify before use Have fireplaces cleaned annually by a chimney sweep  Wood Stove None noted  Course of Action:  None Noted, have an electrician install immediately electrician more added, as needed.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be installed GFIs are older, recommend replacement  Smoke Detectors  None Noted, have an electrician install immediately electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repaired/replaced by electrician more added, an sneeded.  GFIs should be retested & repa	Gas Insert Working	
	Firebox: MetalMasonry	
Abnormal openings (Cracks, missing grout, etc.)  Pire Dirtysharedmissing linerClearance  Damper: Opened and closedCould not open & close safely Broken or missing parts diddid not observe flue liner  Combustion air supply:InteriorExterior air  Dirth was off during inspection  Course of Action:  Have WETT Certified contractor clean, test, evaluate andmasonryMetal prefabricatedWood Stove Insertdhormal openings (Cracks, missing grout, etc.)  Fire Damper:Opened and closedCould not open & close safelySrnoke Detectors  Fire place # 2  None noted	Firebrick loose mortar	
Course of Action:   GFIs should be retested & repaired/replaced by electrician more added, an needed.   GFIs should be installed more added, an needed.   GFIs should be installed more added, an needed.   GFIs are older, recommend replacement	Abnormal openings (Cracks, missing grout, etc.)	All devices tested DID DID NOT trip, as expected.
Demper: Opened and closedCould not open & close safely Broken or missing parts diddid not observe flue linercombustion air supply:InteriorExterior airimittations:Fire burningarea blocked, unable to inspectHave WETT Certified contractor clean, test, evaluate and efficient coation.  Have WETT Certified contractor clean, test, evaluate and entity before useHave fireplaces cleaned annually by a chimney sweep	Flue: Dirty shared missing liner Clearance	
Broken or missing parts did did not observe flue liner Combustion air supply: Interior Exterior air Limitations: Fire burning area blocked, unable to inspect Pilot light was off during inspection  Masory Hetal Masonry Metal prefabricated Wood Stove Insert Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts Abnormal openings (Cracks, missing grout, etc.)  Replace semble detectors  Mone Noted, have an electrician install immediately  #Smoke Detectors  XNot Tested as may be connected to wired / wireless alarm system in house.  *		Course of Action:
did did not observe flue liner combustion air supply: Interior Exterior air imitations:  Pilot light was off during inspection  Pilot l		GFIs should be retested & repaired/replaced by electrician an
Interior	did did not observe flue liner	
Fire burning	combustion air supply: Interior Exterior air	XGFIs should be installed laundry, Kitchen
Pilot light was off during inspection  Nourse of Action:  Have WETT Certified contractor clean, test, evaluate and effity before use  Have fireplaces cleaned annually by a chimney sweep  Fireplace # 2  None noted ocation  Masonry	imitations: Fire burning area blocked unable to inspect	GFIs are older, recommend replacement
with girther was clear annually by a chimney sweep    None noted   Fireplace # 2		
Have WETT Certified contractor clean, test, evaluate and entify before use   Have fireplaces cleaned annually by a chimney sweep		Smoke Detectors ///
# Smoke Detectors    A		
Fireplace # 2  None noted ocation  Masonry Metal prefabricated Wood Stove Insert Gas Insert Working Firebox: Metal Masonry irrebrick loose mortar  Abnormal openings (Cracks, missing grout, etc.)  Broken or missing parts did did not observe flue liner Orombustion air supply: Interior Exterior air Fire burning area blocked, unable to inspect Pilot light was off during inspection  Have WETT Certified contractor clean, test, evaluate and Part Wert fire burning at time of inspection, unable to inspect Have Wet Clearance of Action:  Wood Stove  None noted  None noted  Abnormal openings (Cracks, missing grout, etc.)  Fire burning area blocked, unable to inspect Pilot light was off during inspection  Carbon Monoxide (CO) Detectors  No permanently installed CO detectors noted wired / wireless alarm system in house, they should be tested by alarm compa before sleeping in the house in house.  Course of Action:  Install additional smoke detectors  within 5 feet of bedroom doors  Replace smoke detectors  Relocate smoke detectors  Relocate smoke detectors  A Test smoke detectors monthly  X Test smoke detectors monthly  X Test smoke detectors before sleeping in the house in the house in the properties of Action:  Carbon Monoxide (CO) Detectors  No permanently installed CO detectors noted in house, in house, they should be tested by alarm compa before sleeping in the house in house, in hou	Have WETT Certified contractor clean, test, evaluate and	
Fireplace # 2  None noted ocation  Masonry Metal prefabricated Wood Stove Insert  Gas Insert Working irebox: Metal Masonry irebrick loose mortar  Abnormal openings (Cracks, missing grout, etc.)  June: Dirty shared missing liner Clearance lamper: Opened and closed Could not open & close safely Broken or missing parts did did not observe flue liner combustion air supply: Interior Exterior air imitations:  Fire burning area blocked, unable to inspect Pilot light was off during inspection course of Action:  Have WETT Certified contractor clean, test, evaluate and ertify before use  Have fireplaces cleaned annually by a chimney sweep  Wood Stove  None noted ocation  Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  Install additional smoke detectors upper floor main floor Basement within 5 feet of bedroom doors  Replace smoke detectors  X Test smoke detectors monthly X Test smoke detectors before sleeping in the house No permanently installed CO detectors noted No permanently installed CO detectors noted	ertify before use	#Smoke Detectors
Fireplace # 2  None noted ocation  Masonry Metal prefabricated Wood Stove Insert  Gas Insert Working irebox: Metal Masonry irebrick loose mortar  Abnormal openings (Cracks, missing grout, etc.)  June: Dirty shared missing liner Clearance lamper: Opened and closed Could not open & close safely Broken or missing parts did did not observe flue liner combustion air supply: Interior Exterior air imitations:  Fire burning area blocked, unable to inspect Pilot light was off during inspection course of Action:  Have WETT Certified contractor clean, test, evaluate and ertify before use  Have fireplaces cleaned annually by a chimney sweep  Wood Stove  None noted ocation  Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  Install additional smoke detectors upper floor main floor Basement within 5 feet of bedroom doors  Replace smoke detectors  X Test smoke detectors monthly X Test smoke detectors before sleeping in the house No permanently installed CO detectors noted No permanently installed CO detectors noted	Have fireplaces cleaned annually by a chimney sweep	
None noted ocation		
before sleeping in house.  Course of Action:	Firenlace # 2	alarm system in house, they should be tested by alarm company
Coation		hefore sleening in house
Masonry Metal prefabricated Working Gas Insert Working Working Working Working Working Metal Masonry Working Metal Masonry Working Metal Masonry Within 5 feet of bedroom doors  None noted None noted None noted Pare WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a  WETT Certified Contractor  Working Working Masonry Working Masonry Working Masonry Mosonry Metal Masonry Working Metal Masonry Working Masonry Mose of Action: Install additional smoke detectors  — upper floormain floorBasement Within 5 feet of bedroom doors Replace smoke detectors  — Relocate smoke detectors  — No permanently installed CO detectors noted  ##_CO Detectors		before sleeping in nouse.
Gas Insert	ocation	Course of Action:
we well a masonry   within 5 feet of bedroom doors   Replace smoke detectors   Relocate smoke detectors   Reloca	MasonryMetal pretablicatedvvood Stove insert	
Abnormal openings (Cracks, missing grout, etc.)  ### Abnormal openings (Cracks, missing grout, etc.)  ### Abnormal openings (Cracks, missing grout, etc.)  ### Abnormal openings (Cracks, missing liner Clearance	Gas Insert Working	Install additional smoke detectors
Abnormal openings (Cracks, missing grout, etc.)  Replace smoke detectors  X Test smoke detectors  X Test smoke detectors monthly  X Test smoke detectors before sleeping in the house  Carbon Monoxide (CO) Detectors  No permanently installed CO detectors noted  ###################################	irebox:MetalMasonry	upper 11001main 11001basement
Tue:	irebrickloose mortar	
Amper: Opened and closed	Abnormal openings (Cracks, missing grout, etc.)	Replace smoke detectors
Broken or missing parts diddid not observe flue liner combustion air supply:InteriorExterior air cimitations:Fire burning area blocked, unable to inspectPilot light was off during inspection course of Action:Have WETT Certified contractor clean, test, evaluate and ertify before useHave fireplaces cleaned annually by a chimney sweep None noted cocation Fire burning at time of inspection, unable to inspectHave WETT Certified contractor clean, test and evaluateHave clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor	flue:Dirtysharedmissing linerClearance	Relocate smoke detectors
	Damper:Opened and closedCould not open & close safely	
Combustion air supply:	Broken or missing parts	X Test smoke detectors monthly
	diddid not observe flue liner	X Test smoke detectors before sleeping in the house
	Combustion air supply: InteriorExterior air	
Fire burning area blocked, unable to inspect Pilot light was off during inspection Have WETT Certified contractor clean, test, evaluate and ertify before use Have fireplaces cleaned annually by a chimney sweep Wood Stove None noted Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a Noted Noted, have evaluated for proper operation No permanently installed CO detectors noted # CO Detectors X_Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm comparable for esleeping in house Install CO detector in hall on all sleeping levels at knee X_Test CO detectors before sleeping in the house X_Test CO detectors before sle		Carbon Monoxide (CO) Detectors
Pilot light was off during inspection  Course of Action:  Have WETT Certified contractor clean, test, evaluate and certify before use  Have fireplaces cleaned annually by a chimney sweep  Wood Stove  None noted  Cocation Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a METT Certified Contractor  Mourse of Action:  # CO Detectors  # CO Detectors   *X Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm comparable for sleeping in house.  Install CO detector in hall on all sleeping levels at knee in the house of the contractor clean, test and evaluate in the house of the contractor clean, test and evaluate in the house of the contractor of the		
#CO Detectors    A		No permanently installed CO detectors noted
Have WETT Certified contractor clean, test, evaluate and ertify before use  Have fireplaces cleaned annually by a chimney sweep  Wood Stove  None noted ocation Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  WETT Certified Contractor  Have WETT Certified contractor  Have Clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor		
X Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm comparison before sleeping in house.    None noted		#CO Detectors
Have fireplaces cleaned annually by a chimney sweep  Wood Stove  None noted Ocation Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a  WETT Certified Contractor  Have Gireplaces cleaned annually by a chimney sweep  alarm system in house, they should be tested by alarm comparbefore sleeping in house.  Install CO detector in hall on all sleeping levels at knee of the contractor state of the contractor of the cont		V. Not Tested as may be connected to wired / wireless
Wood Stove  None noted Ocation Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a  WETT Certified Contractor  before sleeping in house.  Replace Carbon Monoxide detectors  X Test CO detectors before sleeping in the house  Interior Fire Sprinkler System  None Noted Noted, have evaluated for proper operation		Not lested as may be conflected to when / wheless
None noted Ocation Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a  WETT Certified Contractor  WETT Certified Contractor  WETT Certified Contractor    Install CO detector in hall on all sleeping levels at knee	Have fireplaces cleaned annually by a chimney sweep	
None noted ocation		
None noted ocation Replace Carbon Monoxide detectors Test CO detectors before sleeping in the house Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a //ETT Certified Contractor  Replace Carbon Monoxide detectors X_Test CO detectors before sleeping in the house Interior Fire Sprinkler System None Noted Noted, have evaluated for proper operation	Wood Stove	Install CO detector in hall on all sleeping levels at knee level
		Replace Carbon Monoxide detectors
Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  Have Clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  Interior Fire Sprinkler System None Noted Noted, have evaluated for proper operation		X Test CO detectors before sleeping in the house
Have WETT Certified contractor clean, test and evaluate  Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  Interior Fire Sprinkler System  None Noted  Noted, have evaluated for proper operation	Fire burning at time of inspection, unable to inspect	
Have clearances of wood stove and flue pipes evaluated by a VETT Certified Contractor  None Noted  Noted, have evaluated for proper operation	Have WETT Certified contractor clean test and evaluate	Interior Fire Sprinkler System
VETT Certified Contractor  Noted, have evaluated for proper operation		X
Light NATT On tiffing any support of a continuous support of the s		
That the tree to the term of t	Have WETT Certified contractor evaluate condition and	Sprinklers are not tested, because to do so would cause flooding and damage to
clearances of wood stove and flue pipes furnishings in the home. Have system evaluated by an appropriate contractor	learances of wood stove and flue pipes	furnishings in the home. Have system evaluated by an appropriate contractor.

Course of Action: Have an electrician install safety devices before sleeping in the home

#### **General Interior**

Ceilings	Doors
DrywallWoodMetalAcoustic ceiling tiles Plaster overWood lathMetal meshwall board Unknown backer material	Mainly door types of:Hollow coreWoodPlasticHinged one sideBi-foldLouveredMirrored Sliders
Appears recently painted / paperedNail pops were noted	Defects noted:
	Some adjustments could be made to the door fit
No major defects were noted	,
Water stains inarea	Doors do not open and close easily
Appears dry, monitor over time	Doors or hinges feel/look loose
The following major defects were noted:	Doors with holes & broken partsDoors missing from opening which normally would be
Walls	expected to have doors.
Drywall Wood Panel coveredPlaster over:Wood lathMetal meshwall board	Doors with missing, broken or damaged hardware / locks
Unknown backer material Unknown materials	Windows
_	Primarily the following types of windows were observed:
No major defeats were noted	Single hung Double hung Casement
No major defects were notedAppears recently painted / paperedNail pops were noted	Sliding Awning Hopper Fixed panes
The following major defects were noted:	SomeMost seem to have insulated glazing (glass)
	They appear to be made of: Wood Metal Plastic
Floors	
Wall to wall carpetRoom sized rugsHardwoodSheet goodsSheet goods	A combination of materialsUnknown
Vinyl tilesCeramic tile	Random tested windows and found
When bounced on,a normal amount of bounce was	Window SashDoDo not open or close under normal
noted excessive bounce was noted	pressure
Slanted floors noted onmainupper floor, monitor for	
ongoing movement	The second secon
Trim	Defects:
None noted (base of walls, around doors & windows)	Broken glass
Mainly, material type of:WoodPlastic	Broken, rotted or loose sash pieces
Trim is Painted Stained Unfinished	Broken or defective counter balance devices
Paint or finish was observed to be peeling.	Missing handles, locks, and hardware
Trim was observed to beloosemissing in	Missing screensDamaged screens, replace
somea fewmost places	Stains, indicating leaks or condensation
	Fogged up / Condensation notedbroken thermal seals
Ctaire Balannias & Bailings	Recommend replace windows for energy conservation
Stairs, Balconies, & Railings	
To BasementTo AtticBetween living levels	
Felt solid under foot, rise and run felt about even	A STATE OF THE PARTY OF THE PAR
Trip hazards observed:	Skylights and Roof Windows
Uneven rise and run from step to step	None noted from interior
Weak or springy treads or stringers	Appear fixedOperateddid not operate
Loose treads Low head room Shallow treads noted	Results:
Loose handrails noted on stairs	Some Most seem to have insulated glazing (glass)
Loose carpet or tread coverings	Leaks (around unit):None noted Small stains noted
Large openings in rail system should be closed down	Excessive staining/damage noted
Steep steps (rise too high)	Condensation/Leaks (abutting glass)None noted
No handrails noted on Basement stairs	Small stains noted Excessive stains noted
Course of Action:	Active water penetration observed
Add handrail for safety	
Railings too low by today's standards, add / adjust for safety	
= Deminis the film by the first a aid file file out a dution for addition	

Course of Action: Have a carpenter or home improvement contractor correct defects noted above

### Attic & Ventilation

Attic Access	Attic Ventilation
No AtticFlat roofCathedral ceiling	No ventilation noted, it may or may not exist
No AccessBlocked by storage items	
No noocoblocked by closings have	Type:
Stairs, see Stairs on INTERIOR page	Ridge vent
	Roof vent
Pull down in	Gable end vent
Access Haldi III	Soffit / Fascia vent
Results:	Turbines
Limited viewing, looked in through opening ONLY	Whole house fan
Due to: low headroom no walkway/floor Storage	Other
Due to:low neadroomlio walkwayillooiotorage	
Entered, walked from end to end	Vents obstructed by:Insulationnest / hives
Entry blocked by excessive storage which also	Volito obolitation b):
the second secon	
prevented sufficient viewing of attic area.  Attic Hatch:  Weatherstrip access hatch	Exhaust venting fans noted in ceilings below attic floor with
AND WALL SMALL	nothing noted in attic to indicate they vent directly to exterior.
Attic Hatch:	ensure properly venting
	Defects:
Moisture / Mildew noted at hatch opening area, repairs needed	Inadequate ventilation, increase venting
	Exhaust fans from interior end in attic and must be
	directed to exterior.
Framing	
Rafters Trusses	Remove insulation that is currently blocking vents, install soff
Observations	baffles
Structural panelsSpaced boards	Soffit vents missing baffles, should be installed
Defects:	
SaggingBuckling	
CrackingRot	Course of Action:
Delaminating	
Course of Action:	
Localized defects, monitor over time	Moisture & Water Penetration
Add or secure structural supports	None noted
Seal party / fire walls	
Sear party / life waits	Evidence observed in attic:
	Dark stains on framing (+yp-ca1)
	Microbial growth / mildew
Attic Storage	
Not recommended	Rust / corrosion on roofing nails
Limited storage	Delaminated or decomposing roof decking material
Attic fully floored	Water damage
	Water stains
	Condensation evident on exhaust pipes
	Course of Action:
	Insulate exhaust vents in attic
	Increase Insulation on pipes
	Have a contractor inspect and repair/rebuild as needed
	Further evaluation and testing for possible mould recommend
	(and remediation work performed as required)
	(200
The state of the s	
Additional Comments or Issues:	
Additional Comments or Issues:	

Course of Action: Have a roofing or other appropriate contractor evaluate and repair as needed.

Page 36 of 38

### Insulation

Attic	Ductwork
None notedAttic could not be accessed	None noted
Fully flooredSome observed, mostly obscured	Somemost ductwork in unconditioned spaces
Form:	was observed to be insulated.
Batt / BlanketLoose FillRigid Board	Insulation appears to beadequateinsufficient
Foamed in Place	Observed:Rust
Type:	Uninsulated ducts should be insulated for energy conservation and to
Glass FiberWood ShavingsMineral Fiber	prevent condensation and resultant damage.
Cellulose FiberUrea Formaldehyde Foam (UFFI)	De la constantina della consta
Plastic/Foam BoardVermiculite, test for Asbestos content	Pipes
Other	None notedHeating cables
Location:	Somemany pipes believed to be carrying heated
FloorRoofBothother	or chilled water or coolants in unconditioned spaces were
D	observed to be insulated.
Estimated thicknessinchesUnknown	Insulation appears to be adequateinsufficient
20	Uninsulated pipes should be insulated for energy conservation and to
Estimated R-valueR	prevent condensation and resultant damage.
Defects:	The state of the s
WetCompressedMildew / fungus	Walls
Evidence of past or current rodent infestation	Not determined
Insulation appears, smells or feels damp/wet, replacing	Through hole in wall(located),
should improve efficiency & reduce allergies.	sawtype of insulation.
Low / bare spots in insulation, recommend additional insulation	
Vapour barrier:None Noted Not visible	Removed #exterior wall outlet covers on interior
PlasticKraft PaperPolyethylene	of house and saw
OtherNot determined	While the above does not determine that the walls are or are not insulated,
Barrier is located on warm side of the insulation	it may give an indication of what is in the walls. Sometimes insulation
Barrier is within insulation or on cold side, have repaired	is placed behind electrical boxes and nowhere else.
Exhaust pipes from interior: (none Visible)	
Adequate insulationwetcondensation	Building Underside
Clearances	Not Applicable
Adequate around pot lights, fans other mechanical items	None noted
Electrical wiring observed within or on top of insulation, have	From within a crawl space / basement, under floor of the
secured.	lowest living areainsulation was observed.
Course of Action:	
Adding additional insulation should be considered to	Estimated thicknessinches thick
ncrease energy efficiency of home.	Estimated R-value ofR.
Additional Comments or Issues:	
Course of Action: Have an appropriate contr	actor replace or add insulation where needed.
	imitations
Normal furnishings and floor, ceiling, and wall coverings will obstruct the	
following items further limited the inspection:	
Exterior	Interior
	Furnishings throughout the house
plantings too close to building	normal minimal,excessive
snow and ice buildupvines on the building	
snow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against	Stored items:
snow and ice buildupvines on the building	Stored items: basement, attic
snow and ice buildupvines on the building debris, leaves, brush, wood or other items piled against exterior of building Other	Stored items:throughout the house,basement,atticnormalminimal,excessive
snow and ice buildupvines on the buildingdebris, leaves, brush, wood or other items piled against exterior of buildingOtherExterior appears recently painted/sided	Stored items: basement, attic

Page 38 of 38